



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	152	<b>Date:</b>	9/21/2004	<b>MeterBasin:</b>	01_WR16
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>	
6314		Greenspring	AVE	
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	100	
<b>Comments:</b>				

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 41

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0921-2004\T-2\PLAYER\_B\B\_2004\_0921Image0041.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 5  
152 (22)

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 7/2/04	Start Time: 1830
Crew: T2	Street Location: Fallstaff Rd		
US MH: 1520982	DS MH: 1520789	Number of Segments: 8	Test Length: 1431'
Plugged US: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Plugged DS: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Moderate <input type="checkbox"/> Wet
Plugs Removed? <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Recorder: Rob Aynk	Comments: CNF 1520978	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Can Not Locate origin of storm line at B4

Last Revised 9/16/2004 Leader Form

Sketch No:

152

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\152.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	152	<b>Date:</b>	9/21/2004	<b>MeterBasin:</b>	01_WR16
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6314		Greenspring	AVE
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	8=Yard-Back
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0
<b>Comments:</b>			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 42

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0921-2004\T-2\PLAYER\_B\B\_2004\_0921Image0042.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 5  
152 (22)

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 7/2/04	Start Time: 1830
Crew: T2	Street Location: Fallstaff Rd		
US MH: 1520982	DS MH: 1520789	Number of Segments: 8	Test Length: 1431'
Plugged US: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Plugged DS: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Moderate <input type="checkbox"/> Wet
Plugs Removed? <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Recorder: Rob Ayuk	Comments: CNF 1520978	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Can Not Locate origin of storm line at B4

Last Revised 9/16/2004 Leader Form

Sketch No:

152

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\152.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	152	<b>Date:</b>	9/21/2004	<b>MeterBasin:</b>	01_WR16
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	4	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6314		Greenspring	AVE

<b>Source Type:</b>	13= Storm Main	<b>Location:</b>	11=Field	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0	

**Comments:** unknown drainage

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 43

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0921-2004\T-2\PLAYER\_B\B\_2004\_0921Image0043.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 5  
152 (22)

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 7/2/04	Start Time: 1830
Crew: T2	Street Location: Fallstaff Rd	Number of Segments: 8	Test Length: 1431'
US MH: 1520982	DS MH: 1520789	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	
Recorder: Rob Ayuk		Comments: CNF 1520978	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Can Not Locate origin of storm line at B4

Last Revised 9/16/2004 Leader Form

Sketch No:

152

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\152.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	153	<b>Date:</b>	9/22/2004	<b>MeterBasin:</b>	01_WR14
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6305		Greenspring	AVE
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0
<b>Comments:</b>			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 44

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0922-2004\T-2\PLAYER\_B\B\_2004\_0922Image0044.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 1  
153

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/22/04	Start Time: 0830
Crew: T2	Street Location: Greenspring Ave	Number of Segments: 7	Test Length: 1454'
US MH: 1520789	DS MH: 1520795	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugged US: (Y) N	Plugged DS: (Y) N	Plugs Removed? (Y) N	
Recorder: Bob Blount		Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

B4 is the smoking drain pipe from the downspout.

Last Revised 9/16/2004      Leader Form

Sketch No: 153

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\153.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	153	<b>Date:</b>	9/22/2004	<b>MeterBasin:</b>	01_WR14
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	6307	<b>Street Prefix:</b>		<b>Street Name:</b>	Greenspring	<b>Street Type:</b>	AVE
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>			
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 45

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0922-2004\T-2\PLAYER\_B\B\_2004\_0922Image0045.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 1  
153

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/22/04	Start Time: 0830
Crew: T2	Street Location: Greenspring Ave	Number of Segments: 7	Test Length: 1454'
US MH: 1520789	DS MH: 1520795	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugged US: (Y) N	Plugged DS: (Y) N	Plugs Removed? (Y) N	Recorder: Bob Blount
Comments:			

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

B4 is the smoking drain pipe from the downspout.

Last Revised 9/16/2004  
Leader Form

Sketch No: 153

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\153.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	153	<b>Date:</b>	9/22/2004	<b>MeterBasin:</b>	01_WR14
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6309		Greenspring	AVE
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	40
<b>Comments:</b>			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 46

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0922-2004\T-2\PLAYER\_B\B\_2004\_0922Image0046.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 1  
153

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/22/04	Start Time: 0830
Crew: T2	Street Location: Greenspring Ave	Number of Segments: 7	Test Length: 1454'
US MH: 1520789	DS MH: 1520795	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugged US: (Y) N	Plugged DS: (Y) N	Recorder: Bob Blount	Comments:
Plugs Removed? (Y) N			

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

B4 is the smoking drain pipe from the downspout.

Last Revised 9/16/2004      Leader Form

Sketch No: 153

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\153.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	153	<b>Date:</b>	9/22/2004	<b>MeterBasin:</b>	01_WR14
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	4	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	6309	<b>Street Prefix:</b>		<b>Street Name:</b>	Greenspring	<b>Street Type:</b>	AVE
<b>Source Type:</b>	07= Area Drain	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>			
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	60				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 47

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0922-2004\T-2\PLAYER\_B\B\_2004\_0922Image0047.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 1  
153

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/22/04	Start Time: 0830
Crew: T2	Street Location: Greenspring Ave	Number of Segments: 7	Test Length: 1454'
US MH: 1520789	DS MH: 1520795	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugged US: (Y) N	Plugged DS: (Y) N	Recorder: Bob Blount	Comments:
Plugs Removed? (Y) N			

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

B4 is the smoking drain pipe from the downspout.

Last Revised 9/16/2004  
Leader Form

Sketch No: 153

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\153.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	153	<b>Date:</b>	9/22/2004	<b>MeterBasin:</b>	01_WR14
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>	
6309		Greenspring	AVE	
<b>Source Type:</b>	05= Downspout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	1000	
<b>Comments:</b>				

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 48

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0922-2004\T-2\PLAYER\_B\B\_2004\_0922Image0048.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 1  
153

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/22/04	Start Time: 0830
Crew: T2	Street Location: Greenspring Ave	Number of Segments: 7	Test Length: 1454'
US MH: 1520789	DS MH: 1520795	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugged US: (Y) N	Plugged DS: (Y) N	Plugs Removed? (Y) N	Recorder: Bob Blount
Comments:			

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

B4 is the smoking drain pipe from the downspout.

Last Revised 9/16/2004  
Leader Form

Sketch No:

153

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\153.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	153	<b>Date:</b>	9/22/2004	<b>MeterBasin:</b>	01_WR14
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	6	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	6311	<b>Street Prefix:</b>		<b>Street Name:</b>	Greenspring	<b>Street Type:</b>	AVE
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>			
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	9				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 49

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0922-2004\T-2\PLAYER\_B\B\_2004\_0922Image0049.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 1  
153

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/22/04	Start Time: 0830
Crew: T2	Street Location: Greenspring Ave	Number of Segments: 7	Test Length: 1454'
US MH: 1520789	DS MH: 1520795	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugged US: (Y) N	Plugged DS: (Y) N	Comments:	
Plugs Removed? (Y) N	Recorder: Bob Blount		

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

B4 is the smoking drain pipe from the downspout.

Last Revised 9/16/2004  
Leader Form

Sketch No: 153

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\153.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	154	<b>Date:</b>	9/22/2004	<b>MeterBasin:</b>	01_WR14
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6309		Fairlane	DR

<b>Source Type:</b>	06= Dwnspt Connect	<b>Location:</b>	6=Curb	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	600	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 50

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0922-2004\T-2\PLAYER\_B\B\_2004\_0922Image0050.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 3  
Smoke Set No. 22  
Setup No. 2  
154

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 9/22/04	Start Time: 1030
Crew: T2	Street Location: Larryvale Road		
US MH: 1520949	DS MH: 1520678	Number of Segments: 7	Test Length: 1373'
Plugged US: Y (N)	Plugged DS: Y (N)	# of Blowers: 1 2 3	Ground: (Dry) Moderate Wet
Plugs Removed? Y (N)	Recorder: Bob Blank	Comments:	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)